

### 100\_B - Asphalt

Street Name:	Amsterdam Road - A	Date Inspected:	6/18/2021
Segment From:	Railroad Trestle (City Line)	Inspected By:	
Segment To:	General Drive	Segment ID:	820

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		1
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	19
Sum of Struc	Sum of Structural Deducts (☑)=		0
		PCR =	81

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 1 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Amsterdam Road - B	Date Inspected:	5/19/2021
Segment From:	General Drive	Inspected By:	
Segment To:	Redwood Drive	Segment ID:	821

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 2 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Amsterdam Road - C	Date Inspected:	6/18/2021
Segment From:	Redwood Drive	Inspected By:	
Segment To:	Park Road	Segment ID:	822

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		1
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		6
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	12
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		88

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 3 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Ann	Date Inspected:	5/19/2021
Segment From:	Lorup	Inspected By:	
Segment To:	End	Segment ID:	856

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		7
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		3
Sum of Defects =		10	
Sum of Structural Deducts (✓)=			0
PCR =		90	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 4 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Ashlawn Place	Date Inspected:	5/19/2021
Segment From:	Highland Avenue	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	621

DISTRESS TYPE		DISTRE: WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		0
Sum of Defects =		ects =	0	
S	Sum of Structural Deducts (☑)=		0	
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 5 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Ashwood Circle	Date Inspected:	6/15/2021
Segment From:	George Huser Drive	Inspected By:	
Segment To:	Dixie Highway	Segment ID:	819

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		2
Patching	12		1
Polished Aggregrate	7		0
	Sum of Def	ects =	10
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	PCR =		90

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 6 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Augusta - A	Date Inspected:	5/19/2021
Segment From:	Rosa	Inspected By:	
Segment To:	Bend	Segment ID:	823

DISTRESS TYPE		DISTRE: WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		15		0
Alligator Cracking		15		0
Bumps Sags		12		0
Deficient Drainage		12		0
Edge Cracking / Raveling		12		0
Patching		12		0
Polished Aggregrate		7		0
		Sum of Defe	ects =	0
	Sum of Structural Deducts (☑)=		0	
		PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 7 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Augusta - B	Date Inspected:	5/19/2021
Segment From:	Bend	Inspected By:	
Segment To:	W Crittenden	Segment ID:	1484

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	4
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		96

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 8 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Barbara Circle	Date Inspected:	5/19/2021
Segment From:	Augusta	Inspected By:	
Segment To:	W Crittenden	Segment ID:	824

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		2
Faulting / Blow-up	12		4
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	6
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 9 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Barrington Road - A	Date Inspected:	5/19/2021
Segment From:	Dixie Highway	Inspected By:	
Segment To:	Park Road	Segment ID:	818

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		2
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		8
Polished Aggregrate	7		0
	Sum of Def	ects =	29
Sum of Struc	Sum of Structural Deducts (☑)=		0
	1	PCR =	71

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 10 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Barrington Road - B	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	602

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		10
Polished Aggregrate	7		0
	Sum of Def	ects =	27
Sum of Struc	Sum of Structural Deducts (☑)=		0
		PCR =	73

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 11 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Basswood Avenue	Date Inspected:	5/19/2021
Segment From:	Henry Clay Avenue	Inspected By:	
Segment To:	cul-de-sac	Segment ID:	580

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	0
Sum of Structural Deducts (☑)=			0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 12 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Beacon Hill Drive - A (Entrance	Date Inspected:	5/19/2021
Segment From:	Mount Vernon	Inspected By:	
Segment To:	Beacon Hill	Segment ID:	1485

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	18
Sum of Structural Deducts (☑)=		0	
	PCR =		82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 13 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Beacon Hill Drive - B	Date Inspected:	5/19/2021
Segment From:	Cul-de-Sac	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	634

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		0
Sum of Defects =		0		
Sum of Structural Deducts (☑)=		0		
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 14 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Beaumont Court - A	Date Inspected:	5/19/2021
Segment From:	Highland Pike	Inspected By:	
Segment To:	Mount Vernon Drive	Segment ID:	816

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		6
Patching	12		0
Polished Aggregrate	7		0
Sum of Defects =		16	
Sum of Structural Deducts (☑)=		0	
	PCR =		84

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 15 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Beaumont Court - B	Date Inspected:	5/19/2021
Segment From:	Mt. Vernon Drive	Inspected By:	
Segment To:	Montpelier Court	Segment ID:	632

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	2
Sum of Structural Deducts (☑)=		s (☑)=	0
PCR =		98	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 16 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Birchwood Drive	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Amsterdam Road	Segment ID:	807

DISTRESS TYPE	DISTRI WEIG		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		0	
Sum of Structural Deducts (☑)=			0
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes: scheduled for reconstruction 2021

Page 17 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Bluegrass Avenue	Date Inspected:	5/19/2021
Segment From:	Henry Clay Street	Inspected By:	
Segment To:	end	Segment ID:	628

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		1
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
Sum of Defects =		13	
Sum of Structural Deducts (☑)=		0	
	1	PCR =	87

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 18 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Bunker	Date Inspected:	5/19/2021
Segment From:	end	Inspected By:	
Segment To:	Fort Henry	Segment ID:	825

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		2
Polished Aggregrate	7		4
Sum of Defects =		27	
Sum of Structural Deducts (☑)=		s ( <u>√</u> )=	0
PCR =		73	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 19 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Cherokee	Date Inspected:	5/19/2021
Segment From:	End	Inspected By:	
Segment To:	Morris	Segment ID:	826

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		5
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
Sum of Defects =		ects =	21
Sum of Structural Deducts (☑)=			0
	PCR =		79

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 20 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Chestnut Court	Date Inspected:	5/19/2021
Segment From:	Redwood Drive	Inspected By:	
Segment To:	cul-de-sac	Segment ID:	604

DISTRESS TYPE	DISTRES WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		8
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		1
Joint Condition	10		0
Sum of Defects =			9
Sum of Structural Deducts (☑)=			0
PCR =		91	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 21 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Christine Court	Date Inspected:	5/19/2021
Segment From:	Henry Clay Avenue	Inspected By:	
Segment To:	End	Segment ID:	581

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
Sum of Defects =		0	
Sum of Structural Deducts (☑)=		s (☑)=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 22 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Cumberland Avenue	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Basswood Avenue	Segment ID:	583

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =			0
Sum of Structural Deducts (☑)=			0
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 26 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Don Martin	Date Inspected:	5/19/2021
Segment From:	Lookout Heights	Inspected By:	
Segment To:	End	Segment ID:	855

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		2
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		0
Sum of Defects =		ects =	2	
Sum of Structural Deducts (☑)=			s ( <b>☑</b> )=	0
PCR =		98		

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 27 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Dorisway Drive	Date Inspected:	5/19/2021
Segment From:	Williams Creek Way	Inspected By:	
Segment To:	End	Segment ID:	1486

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	6
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 28 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Dudley	Date Inspected:	6/17/2021
Segment From:	Madison Pike	Inspected By:	
Segment To:	End	Segment ID:	827

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	2
Sum of Structural Deducts (☑)=		s (🗹)=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 29 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	E Crittenden Avenue	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Basswood Avenue	Segment ID:	582

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		fects =	0
Sum of Structural Deducts (☑)=		0	
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 30 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	E Henry Clay - A	Date Inspected:	5/19/2021
Segment From:	Kyles	Inspected By:	
Segment To:	Henry Clay Ct	Segment ID:	829

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		s (☑)=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 31 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	E Henry Clay - B	Date Inspected:	5/19/2021
Segment From:	Henry Clay Ct	Inspected By:	
Segment To:	Upland	Segment ID:	828

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		1
Polished Aggregrate	7		0
	Sum of Def	ects =	12
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
PCR =		88	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 32 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	E Henry Clay - C	Date Inspected:	5/19/2021
Segment From:	Upland	Inspected By:	
Segment To:	Highland	Segment ID:	1487

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		4
Polished Aggregrate	7		0
	Sum of Def	ects =	15
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
PCR =		85	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 33 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Eaton Drive	Date Inspected:	5/19/2021
Segment From:	Madison Pike (KY17)	Inspected By:	
Segment To:	Bridge	Segment ID:	815

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		7
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	20
Sum of Structural Deducts (☑)=		0	
	PCR =		80

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 34 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Edna Lane	Date Inspected:	5/19/2021
Segment From:	Augusta	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	587

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		0	
Sum of Structural Deducts (☑)=		0	
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 35 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Elder Court	Date Inspected:	5/19/2021
Segment From:	Redwood Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	605

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		3
Transverse Longitudinal Cracking		12		8
Corner / Diagonal Cracks		12		6
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		6
Polished Aggregate		5		0
Joint Condition		10		6
Sum of Defects =		29		
Sum of Structural Deducts (☑)=		0		
PCR =		71		

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 36 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Farrell	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Private Drive	Segment ID:	830

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		6
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		4
Polished Aggregrate	7		0
	Sum of Defe	ects =	28
Sum of Structural Deducts (☑)=		0	
	F	PCR =	72

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 37 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Fayette	Date Inspected:	5/19/2021
Segment From:	E Henry Clay	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	831

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	13
Sum of Structural Deducts (☑)=		0	
	ı	PCR =	87

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 38 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Fort Henry Drive - A	Date Inspected:	5/19/2021
Segment From:	Amsterdam Road	Inspected By:	
Segment To:	422 Fort Henry	Segment ID:	608

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		16
Alligator Cracking	15		12
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		16
Patching	12		0
Polished Aggregrate	7		0
Sum of Defects =		51	
Sum of Structural Deducts (☑)=		0	
		PCR =	49

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 39 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Fort Henry Drive - B	Date Inspected:	5/19/2021
Segment From:	422 Fort Henry	Inspected By:	
Segment To:	434 Fort Henry	Segment ID:	1488

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		4
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	6
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
PCR =		94	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 40 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Fort Henry Drive - C	Date Inspected:	5/19/2021
Segment From:	434 Fort Henry	Inspected By:	
Segment To:	Lookout Ct	Segment ID:	1489

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		16
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		16
Patching	12		12
Polished Aggregrate	7		0
	Sum of Def	ects =	50
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		50

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 41 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Fort Henry Drive - D	Date Inspected:	5/19/2021
Segment From:	Lookout Court	Inspected By:	
Segment To:	Pickett Drive	Segment ID:	649

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		12
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		9
Bumps Sags	12		8
Deficient Drainage	12		0
Edge Cracking / Raveling	12		16
Patching	12		4
Polished Aggregrate	7		0
	Sum of Defe	ects =	56
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		44

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 42 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Fort Henry Drive - E	Date Inspected:	5/19/2021
Segment From:	Pickett Drive	Inspected By:	
Segment To:	General Drive	Segment ID:	610

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		12
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		9
Bumps Sags	12		8
Deficient Drainage	12		0
Edge Cracking / Raveling	12		16
Patching	12		4
Polished Aggregrate	7		0
Sum of Defects =		ects =	56
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	1	PCR =	44

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 43 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	General Drive - A	Date Inspected:	5/19/2021
Segment From:	Amsterdam Road	Inspected By:	
Segment To:	Pickett Drive	Segment ID:	651

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
Sum of Defects =		ects =	19
Sum of Structural Deducts (☑)=		0	
	ı	PCR =	81

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 44 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	General Drive - B	Date Inspected:	5/19/2021
Segment From:	Pickett Drive	Inspected By:	
Segment To:	High Point Drive	Segment ID:	650

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		12
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
	Sum of Defe	ects =	28
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	PCR =		72

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 45 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	General Drive - C	Date Inspected:	5/19/2021
Segment From:	High Point Drive	Inspected By:	
Segment To:	Fort Henry Drive	Segment ID:	611

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		1
	Sum of Def	ects =	24
Sum of Struc	Sum of Structural Deducts (☑)=		0
		PCR =	76

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 46 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	General Drive - D	Date Inspected:	5/19/2021
Segment From:	Fort Henry Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	1490

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		1
	Sum of Def	ects =	24
Sum of Structural Deducts (☑)=		's ( <b>☑</b> )=	0
	PCR =		76

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 47 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	George Huser Drive	Date Inspected:	5/19/2021
Segment From:	Dixie Highway	Inspected By:	
Segment To:	Park Road	Segment ID:	817

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	15
Sum of Struc	Sum of Structural Deducts (☑)=		0
	ı	PCR =	85

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 48 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Glasgow Court	Date Inspected:	5/19/2021
Segment From:	Glengarry Way	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	643

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		1
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	20
Sum of Structural Deducts (☑)=		0	
	1	PCR =	80

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 49 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Glazier Court	Date Inspected:	6/15/2021
Segment From:	Barrington Road	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	607

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		3
Transverse Longitudinal Cracking		12		8
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		8
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		2
		Sum of Def	ects =	21
Sum of Structural Deducts (☑)=		0		
	PCR =		79	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 50 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Glazier Road	Date Inspected:	5/19/2021
Segment From:	Morris Place	Inspected By:	
Segment To:	Barrington	Segment ID:	603

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	2
Sum of Structural Deducts (☑)=		s (☑)=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 51 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Glengarry Way	Date Inspected:	5/19/2021
Segment From:	Fort Henry Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	802

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		1
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	20
Sum of Structural Deducts (☑)=		0	
		PCR =	80

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 52 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Goebel Court	Date Inspected:	5/19/2021
Segment From:	Morris Road	Inspected By:	
Segment To:	cul-de-sac	Segment ID:	606

DISTRESS TYPE		DISTRE: WEIGH		RATING
Pot Holes		15		3
Transverse Longitudinal Cracking		12		2
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		2
Sum of Defects =		ects =	7	
Su	Sum of Structural Deducts (☑)=		0	
	PCR =		93	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 53 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Grove Park Dr	Date Inspected:	5/19/2021
Segment From:	Park Rd	Inspected By:	
Segment To:	Lemon Tree	Segment ID:	2018

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		0	
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes: under construction at the time of rating

Page 54 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Hazlewood Drive	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Redwood Drive	Segment ID:	806

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		12
Bumps Sags	12		12
Deficient Drainage	12		1
Edge Cracking / Raveling	12		8
Patching	12		4
Polished Aggregrate	7		4
	Sum of Defe	ects =	48
Sum of Struc	Sum of Structural Deducts (☑)=		0
	1	PCR =	52

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 55 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Helen Ruth	Date Inspected:	5/19/2021
Segment From:	Old KY17	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	653

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		0	
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 57 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Henry Clay Court	Date Inspected:	5/19/2021
Segment From:	E. Henry Clay Ave.	Inspected By:	
Segment To:	End	Segment ID:	1945

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		1
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		2
Patching	12		0
Polished Aggregrate	7		0
	Sum of De	fects =	7
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		93

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 58 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Hermitage	Date Inspected:	5/19/2021
Segment From:	Monticello	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	832

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		2
Sum of Defects =		ects =	2	
Sum of Structural Deducts (☑)=			s ( <b>▽</b> )=	0
	PCR =		98	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 59 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	High Point Drive	Date Inspected:	5/19/2021
Segment From:	General Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	598

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		0	
Sum of Structural Deducts (✓)=		s (🗸 )=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 60 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Highland Pike	Date Inspected:	6/18/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	City Line/Covington	Segment ID:	1491

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	16
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	1	PCR =	84

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 61 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Highland Place	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	End	Segment ID:	833

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
	Sum of Defe	ects =	19
Sum of Structural Deducts (☑)=		0	
	ı	PCR =	81

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 62 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Highview Drive	Date Inspected:	5/19/2021
Segment From:	Rivard	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	585

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		1
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	8
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		92

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 63 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Howard Road	Date Inspected:	5/19/2021
Segment From:	Barrington Road	Inspected By:	
Segment To:	Morris Road	Segment ID:	601

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		6
Polished Aggregrate	7		0
	Sum of De	fects =	26
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
PCR =		74	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 64 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Kennedy - A	Date Inspected:	5/19/2021
Segment From:	Kyles	Inspected By:	
Segment To:	Rosa	Segment ID:	834

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		s (☑)=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 65 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Kennedy - B	Date Inspected: 5	5/19/2021
Segment From:	Rosa	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	835

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		2
Patching	10		1
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		3	
Sum of Structural Deducts (☑)=			0
	PCR =		97

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 66 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Kentucky	Date Inspected:	5/19/2021
Segment From:	Highland	Inspected By:	
Segment To:	Lorup	Segment ID:	836

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 67 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Knob Hill	Date Inspected:	5/19/2021
Segment From:	Mt. Vernon	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	837

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		3
Polished Aggregate		5		0
Joint Condition		10		2
Sum of Defects =		5		
Sum of Structural Deducts (☑)=		0		
	PCR =		95	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 68 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Kyles Place	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	End	Segment ID:	1492

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 69 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Lake Street - A	Date Inspected:	5/19/2021
Segment From:	Kennedy Rd	Inspected By:	
Segment To:	North Cul-de-Sac	Segment ID:	838

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =			2
Sum of Structural Deducts (☑)=			0
PCR =		98	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 70 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Lake Street - B	Date Inspected:	5/19/2021
Segment From:	Kennedy Road	Inspected By:	
Segment To:	South Cul-de-Sac	Segment ID:	1493

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	2
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
PCR =		98	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 71 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Lemon Tree Ln	Date Inspected:	5/19/2021
Segment From:	End (Grove Park)	Inspected By:	
Segment To:	End	Segment ID:	2016

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		s (☑)=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes: under construction at the time of inventory

Page 72 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Lookout Court	Date Inspected:	5/19/2021
Segment From:	Fort Henry	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	839

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	15
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		85

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 73 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Lookout Heights Lane	Date Inspected:	6/15/2021
Segment From:	Sleepy Hollow Road	Inspected By:	
Segment To:	End	Segment ID:	814

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		4
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		ects =	10
Sum of Structural Deducts (☑)=		0	
PCR =		90	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 74 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Lorup Avenue	Date Inspected:	6/17/2021
Segment From:	Highland Pike	Inspected By:	
Segment To:	Kyles Lane	Segment ID:	809

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		1
Alligator Cracking	15		0
Bumps Sags	12		1
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		1
Polished Aggregrate	7		0
	Sum of Def	ects =	3
Sum of Structural Deducts (☑)=		's ( <b>▽</b> )=	0
		PCR =	97

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 75 of 133 DATE PRINTED: 9/8/2021



## 100\_B - Asphalt

Street Name:	Marcella	Date Inspected:	5/19/2021
Segment From:	St. Anthony	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	840

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Det	fects =	6
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 76 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Monticello Drive - A	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Ashlawn Place	Segment ID:	1495

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		8
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Del	fects =	27
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
PCR =		73	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 77 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Monticello Drive - B	Date Inspected:	5/19/2021
Segment From:	Ashlawn Place	Inspected By:	
Segment To:	Normandy	Segment ID:	623

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		fects =	0
Sum of Structural Deducts (☑)=		0	
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 78 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Monticello Drive - C	Date Inspected:	5/19/2021
Segment From:	Normandy	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	1494

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Dea	fects =	12
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
PCR =		88	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 80 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Montpelier	Date Inspected:	5/19/2021
Segment From:	Mt. Vernon	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	842

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		3
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		ects =	9
Sum of Structural Deducts (☑)=		s (🗹)=	0
	PCR =		91

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 81 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Morris Place	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Glazier Court	Segment ID:	619

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	2
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
PCR =		98	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 82 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Morris Road - A	Date Inspected:	5/19/2021
Segment From:	Amsterdam Road	Inspected By:	
Segment To:	Howard Road	Segment ID:	600

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		6
Polished Aggregrate	7		0
	Sum of Def	ects =	29
Sum of Structural Deducts (☑)=		0	
	PCR =		71

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 83 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Morris Road - B	Date Inspected:	5/19/2021
Segment From:	Amsterdam Rd	Inspected By:	
Segment To:	Cherokee Dr	Segment ID:	1496

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		2
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		4
Polished Aggregrate	7		0
	Sum of Def	ects =	20
Sum of Structural Deducts (☑)=		0	
	PCR =		80

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 84 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Morris Road - C	Date Inspected:	5/19/2021
Segment From:	Cherokee Dr	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	631

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		8
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		4
Patching	10		3
Polished Aggregate	5		0
Joint Condition	10		2
Sum of Defects =		ects =	17
Sum of Structural Deducts (✓)=		s ( <b>▽</b> )=	0
	PCR =		83

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 85 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - A	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Beaumont Court	Segment ID:	812

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		5
Bumps Sags	12		1
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	18
Sum of Structural Deducts (☑)=		0	
	PCR =		82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 86 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - B	Date Inspected:	6/17/2021
Segment From:	Beaumont Court	Inspected By:	
Segment To:	Beacon Hill Drive	Segment ID:	813

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		4
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		1
Polished Aggregrate	7		0
Sum of Defects =		9	
Sum of Structural Deducts (☑)=		0	
	PCR =		91

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 87 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - C	Date Inspected:	5/19/2021
Segment From:	Beacon Hill Drive	Inspected By:	
Segment To:	1923	Segment ID:	635

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		3
Bumps Sags	12		1
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	12
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	PCR =		88

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 88 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Mount Vernon Drive - D	Date Inspected:	5/19/2021
Segment From:	1923	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	2020

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		4
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		1
Polished Aggregrate	7		0
Sum of Defects =		16	
Sum of Structural Deducts (☑)=		0	
	ı	PCR =	84

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 89 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Normandy Court	Date Inspected:	5/19/2021
Segment From:	Monticello Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	622

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		fects =	0
Sum of Structural Deducts (☑)=		0	
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 90 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Oak Hill Court	Date Inspected:	5/19/2021
Segment From:	Mt. Vernon Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	626

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		0
Sum of Defects =		0		
Sum of Structural Deducts (☑)=		0		
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 91 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Old Horsebranch Road	Date Inspected:	5/19/2021
Segment From:	Orphanage Road	Inspected By:	
Segment To:	End	Segment ID:	811

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	0
Sum of Structural Deducts (☑)=		0	
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 92 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Old KY 17	Date Inspected:	5/19/2021
Segment From:	Madison Pike	Inspected By:	
Segment To:	city line	Segment ID:	652

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		15
Bumps Sags	12		12
Deficient Drainage	12		0
Edge Cracking / Raveling	12		16
Patching	12		8
Polished Aggregrate	7		0
Sum of Defects =		61	
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	ı	PCR =	39

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 93 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Old State Road	Date Inspected:	5/19/2021
Segment From:	Sleepy Hollow Road	Inspected By:	
Segment To:	City Line	Segment ID:	629

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Defe	ects =	18
Sum of Struc	Sum of Structural Deducts (☑)=		0
	ı	PCR =	82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 94 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Olivia	Date Inspected:	5/19/2021
Segment From:	Highland	Inspected By:	
Segment To:	Lorup	Segment ID:	843

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 95 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Orange Blossom Ct	Date Inspected:	5/19/2021
Segment From:	Grove Park	Inspected By:	
Segment To:	End	Segment ID:	2017

DISTRESS TYPE		DISTRE: WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		15		0
Alligator Cracking		15		0
Bumps Sags		12		0
Deficient Drainage		12		0
Edge Cracking / Raveling		12		0
Patching		12		0
Polished Aggregrate		7		0
		Sum of Defe	ects =	0
	Sum of Structural Deducts (☑)=		0	
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes: under construction at the time of rating

Page 96 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Park Road	Date Inspected:	5/19/2021
Segment From:	Morris	Inspected By:	
Segment To:	Barrington	Segment ID:	844

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		4
Polished Aggregrate	7		0
	Sum of Def	ects =	19
Sum of Structural Deducts (☑)=		0	
	PCR =		81

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 97 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Parkside Place	Date Inspected:	5/19/2021
Segment From:	Cul-de-Sac	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	637

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		4
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		3
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		ects =	15
Sum of Structural Deducts (☑)=		0	
PCR =		85	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 98 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Pickett Ct	Date Inspected:	5/19/2021
Segment From:	Pickett Dr	Inspected By:	
Segment To:	Cul-se-Sac	Segment ID:	1498

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
	Sum of Defe	ects =	23
Sum of Structural Deducts (☑)=		s ( <b>▽</b> )=	0
	ı	PCR =	77

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 99 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Pickett Drive - A	Date Inspected:	5/19/2021
Segment From:	General Drive	Inspected By:	
Segment To:	Pickett Court	Segment ID:	599

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		2
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Det	fects =	21
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
PCR =		79	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 100 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Pickett Drive - B	Date Inspected:	5/19/2021
Segment From:	Pickett Ct	Inspected By:	
Segment To:	Fort Henry	Segment ID:	1497

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		1
Polished Aggregrate	7		0
	Sum of Def	ects =	23
Sum of Structural Deducts (☑)=		0	
	PCR =		77

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 101 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Pieck Drive - A	Date Inspected:	5/19/2021
Segment From:	City Line	Inspected By:	
Segment To:	#1995	Segment ID:	641

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of De	fects =	0
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 102 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Pieck Drive - B	Date Inspected:	5/19/2021
Segment From:	#1995	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	642

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		1
Polished Aggregrate	7		0
	Sum of De	fects =	8
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		92

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 103 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Pine Hurst	Date Inspected:	5/19/2021
Segment From:	Cul-de-Sac	Inspected By:	
Segment To:	City Line	Segment ID:	845

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		4
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		2
Sum of Defects =		ects =	8
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
PCR =		92	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 104 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Redwood Drive	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Amsterdam Road	Segment ID:	805

DISTRESS TYPE		DISTRE WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		12		0
Corner / Diagonal Cracks		12		0
Faulting / Blow-up		12		0
Scaling / Spauling		12		0
Deficient Drainage		12		0
Patching		10		0
Polished Aggregate		5		0
Joint Condition		10		0
Sum of Defects =		ects =	0	
Sum of Structural Deducts (☑)=			s ( <b>☑</b> )=	0
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes: scheduled for 2021

Page 105 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Reeves Drive	Date Inspected:	5/19/2021
Segment From:	Highland Avenue	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	625

DISTRESS TYPE	DISTRE: WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		2
Polished Aggregrate	7		0
Sum of Defects =		6	
Sum of Struc	Sum of Structural Deducts (☑)=		0
	ı	PCR =	94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 106 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Ridgemont	Date Inspected:	5/19/2021
Segment From:	Henry Clay	Inspected By:	
Segment To:	End	Segment ID:	846

DISTRESS TYPE	DISTRI WEIG		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =			0
Sum of Structural Deducts (☑)=			0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 107 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Rivard Drive - A	Date Inspected:	5/19/2021
Segment From:	Kennedy	Inspected By:	
Segment To:	Highview	Segment ID:	586

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		1
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 108 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Rivard Drive - B	Date Inspected:	5/19/2021
Segment From:	High View	Inspected By:	
Segment To:	Dixie	Segment ID:	847

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		1
Transverse Longitudinal Cracking	15		1
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 109 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Rosa Ave	Date Inspected:	5/19/2021
Segment From:	W. Crittenden	Inspected By:	
Segment To:	Kennedy	Segment ID:	848

DISTRESS TYPE	DISTRE WEIGI		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of De	fects =	2
Sum of Structural Deducts (☑)=		0	
		PCR =	98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 110 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Rosa Ct	Date Inspected:	5/19/2021
Segment From:	Kennedy	Inspected By:	
Segment To:	End	Segment ID:	1499

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		4
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		3
Joint Condition	10		0
Sum of Defects =		fects =	7
Sum of Structural Deducts (✓)=		ts ( <b>☑</b> )=	0
	PCR =		93

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 111 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Sentinel Point	Date Inspected:	5/19/2021
Segment From:	General	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	849

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	22
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
		PCR =	78

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 112 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	St. Agnes Circle	Date Inspected:	5/19/2021
Segment From:	Park Road	Inspected By:	
Segment To:	Vidot Court	Segment ID:	588

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		2
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		2
Sum of Defects =		ects =	6
Sum of Structural Deducts (✓)=		s ( <b>☑</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 114 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	St. Anthony	Date Inspected:	5/19/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	End	Segment ID:	841

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		1
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		1
Polished Aggregrate	7		0
Sum of Defects =		6	
Sum of Structural Deducts (☑)=			0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 115 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Stonewell Trail	Date Inspected:	5/19/2021
Segment From:	Longmeadow	Inspected By:	
Segment To:	Parkside Place	Segment ID:	636

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		4
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		4
Patching	10		6
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		20	
Sum of Structural Deducts (☑)=			0
PCR =		80	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 116 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Stoney Point	Date Inspected:	5/19/2021
Segment From:	General	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	850

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		0
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =			0
Sum of Structural Deducts (☑)=			0
PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 117 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Tartan Drive	Date Inspected:	5/19/2021
Segment From:	Glengarry Way	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	803

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		7
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
Sum of Defects =		18	
Sum of Structural Deducts (☑)=		0	
	PCR =		82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 118 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Tyler Court	Date Inspected:	5/19/2021
Segment From:	Fort Henry Drive	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	630

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		8
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		4
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		ects =	18
Sum of Structural Deducts (☑)=			0
PCR =		82	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 119 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Upland	Date Inspected:	5/19/2021
Segment From:	Henry Clay	Inspected By:	
Segment To:	End	Segment ID:	851

DISTRESS TYPE		DISTRE: WEIGH		RATING
Pot Holes		15		0
Transverse Longitudinal Cracking		15		0
Alligator Cracking		15		0
Bumps Sags		12		0
Deficient Drainage		12		0
Edge Cracking / Raveling		12		0
Patching		12		0
Polished Aggregrate		7		0
		Sum of Defe	ects =	0
	Sum of Structural Deducts (☑)=		0	
	PCR =		100	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 120 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Valley Drive	Date Inspected:	6/17/2021
Segment From:	Kyles Lane	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	645

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		3
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		4
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		3
Polished Aggregate	5		0
Joint Condition	10		6
Sum of Defects =		ects =	18
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 121 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Valley Plaza Parkway	Date Inspected:	5/19/2021
Segment From:	Highland Pike	Inspected By:	
Segment To:	Orphanage Road	Segment ID:	810

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		6
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		8
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	18
Sum of Structural Deducts (☑)=		0	
	1	PCR =	82

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 122 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Vidot Court	Date Inspected:	5/19/2021
Segment From:	Amsterdam Road	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	596

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		8
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		0
Polished Aggregate	5		0
Joint Condition	10		2
Sum of Defects =		ects =	10
Sum of Structural Deducts (☑)=		s ( <u>v</u> )=	0
PCR =		90	

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 123 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Viewpoint Drive	Date Inspected:	5/19/2021
Segment From:	Valley Plaza Parkway	Inspected By:	
Segment To:	end of pavement	Segment ID:	594

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		5
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		2
Polished Aggregrate	7		0
	Sum of Def	ects =	11
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		89

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 124 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	W Crittenden	Date Inspected:	5/19/2021
Segment From:	Barbara	Inspected By:	
Segment To:	Kyles	Segment ID:	853

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Structural Deducts (✓)=		s ( <b>▽</b> )=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 126 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	W Henry Clay - A	Date Inspected:	5/19/2021
Segment From:	Rosa	Inspected By:	
Segment To:	#8 W Henry Clay	Segment ID:	852

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		2
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	2
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		98

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 127 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	W Henry Clay - B	Date Inspected:	5/19/2021
Segment From:	#8 W Henry Clay	Inspected By:	
Segment To:	Kyles	Segment ID:	1946

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		3
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Def	ects =	7
Sum of Struc	Sum of Structural Deducts (☑)=		0
	PCR =		93

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 128 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Werner Drive A	Date Inspected:	5/19/2021
Segment From:	Highland Pk	Inspected By:	
Segment To:	Bend	Segment ID:	2019

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		4
Alligator Cracking	15		0
Bumps Sags	12		4
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of De	fects =	12
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		88

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 129 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Werner Drive B	Date Inspected:	5/19/2021
Segment From:	Bend	Inspected By:	
Segment To:	Lorup Avenue	Segment ID:	808

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		0
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		0
Polished Aggregrate	7		0
	Sum of De	fects =	0
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		100

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 130 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Williams Creek	Date Inspected:	5/19/2021
Segment From:	end	Inspected By:	
Segment To:	Old Ky 17	Segment ID:	854

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		0
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		4
Patching	12		0
Polished Aggregrate	7		0
	Sum of Det	fects =	6
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 131 of 133 DATE PRINTED: 9/8/2021



#### 100\_B - Concrete

Street Name:	Wolfzorn Court	Date Inspected:	5/19/2021
Segment From:	Mt. Vernon	Inspected By:	
Segment To:	Cul-de-Sac	Segment ID:	624

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	12		2
Corner / Diagonal Cracks	12		0
Faulting / Blow-up	12		0
Scaling / Spauling	12		0
Deficient Drainage	12		0
Patching	10		3
Polished Aggregate	5		0
Joint Condition	10		0
Sum of Defects =		ects =	5
Sum of Structural Deducts (☑)=		s ( <b>☑</b> )=	0
	PCR =		95

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 132 of 133 DATE PRINTED: 9/8/2021



### 100\_B - Asphalt

Street Name:	Wrights Summit Parkway	Date Inspected:	5/19/2021
Segment From:	Dixie Highway	Inspected By:	
Segment To:	Kyles Lane	Segment ID:	648

DISTRESS TYPE	DISTRE WEIGH		RATING
Pot Holes	15		0
Transverse Longitudinal Cracking	15		2
Alligator Cracking	15		3
Bumps Sags	12		0
Deficient Drainage	12		0
Edge Cracking / Raveling	12		0
Patching	12		1
Polished Aggregrate	7		0
	Sum of Det	fects =	6
Sum of Structural Deducts (☑)=		ts ( <b>☑</b> )=	0
	PCR =		94

Pavement Condition Rating (PCR) = 100 - (Sum of Defects + Sum of Structural Deducts)

Notes:

Page 133 of 133 DATE PRINTED: 9/8/2021